



NATIONAL FIBER
CEL-PAK INSULATION

Professional Cellulose for Cellulose Professionals

UL Approved Fire Assemblies with NuWool Cellulose Insulation

Wall Assemblies

Design #	Fire Rating	Finish Rating	Type
U023	2 Hour	-	Nonbearing
U032	1 Hour	-	Bearing
U040	1 Hour	-	Nonbearing
U053	1 Hour	-	Nonbearing
U305	1 Hour	20 - 26 Min	Bearing
U307	1 Hour	25 Min	Bearing
U309	1 Hour	27 Min	Bearing
U311	1 Hour	23 Min	Bearing
U317	45 Min	15 & 20 Min	Bearing
U321	1 Hour	38 Min	Bearing
U333	1 Hour	23 Min	Bearing
U338	1 Hour	20 & 59 Min	Bearing
U339	1 Hour	20 & 59 Min	Bearing
U341	1 Hour	20 Min	Bearing
U342	2 Hour	59 Min	Bearing
U344	1 Hour	26 Min	Bearing
U354	1 Hour	24 Min	Bearing
U356	1 Hour	23 Min	Bearing
U360	2 Hour	20 Min	Bearing
U369	2 Hour	-	Bearing
U382	2.5 Hour	-	Bearing
U403	2 Hour	-	Nonbearing
U411	2 Hour	-	Nonbearing
U412	2 Hour	-	Nonbearing
U420	1 or 2 Hour	-	Nonbearing
U425	45 Min - 2 Hr	-	Bearing
U426	3 Hour	-	Bearing
U428	2 Hour	-	Nonbearing
U429	2 Hour	-	Nonbearing

Design #	Fire Rating	Type
U434	1 Hour	Bearing
U435	3 or 4 Hour	Nonbearing
U436	1, 2 or 3 Hour	Nonbearing
U438	2 Hour	Nonbearing
U440	1 Hour	Bearing
U462	3 Hour	Bearing
U463	3 or 4 Hour	Nonbearing
U465	1 Hour	Nonbearing
U466	1 Hour	Nonbearing
U467	2 Hour	Nonbearing
U469	1 Hour	Nonbearing
U477	2 Hour	Bearing
U478	3 Hour	Nonbearing
U495	1 or 2 Hour	Nonbearing
U498	2 Hour	Nonbearing
U499	1 Hour	Nonbearing
U603	3 Hour	Nonbearing
U611	2 Hour	Nonbearing
U614	2 Hour	Nonbearing
U618	2 Hour	Nonbearing
U622	1 Hour	Nonbearing
U646	1 Hour	Nonbearing
U647	2 Hour	Nonbearing
V410	2 Hour	Nonbearing
V416	1 Hour	Nonbearing
V421	1 and 2 Hour	Nonbearing
V455	1 and 2 Hour	Nonbearing
V472	2 Hour	Nonbearing
V481	1, 2 or 3 Hour	Nonbearing

Floor & Ceiling Assemblies

Design #	Company	Fire Rating	Type	Restrained Assembly	
G540	Generic	1 and 2 Hour	Floor / Ceiling	Y	
G542	Generic	1 and 2 Hour	Floor / Ceiling	Y	
G543	Generic	1 Hour	Floor / Ceiling	Y	
G544	Generic	1 Hour	Floor / Ceiling	Y	
G545	Generic	2 Hour	Floor / Ceiling	Y	
G546	Generic	1 Hour	Floor / Ceiling	Y	
L549	Generic	1 Hour	Floor / Ceiling	N	
L550	Generic	1 Hour	Floor / Ceiling	N	
L551	Generic	1 Hour	Floor / Ceiling	N	
L552	Generic	1 Hour	Floor / Ceiling	N	
L558	Generic	1 Hour	Floor / Ceiling	N	
L559	Generic	1 Hour	Floor / Ceiling	N	
L560	Generic	1 Hour	Floor / Ceiling	N	
L563	Generic	1 Hour	Floor / Ceiling	N	
L565	Generic	1 Hour	Floor / Ceiling	N	
L569	Generic	1 Hour	Floor / Ceiling	N	
L570	Generic	1 Hour	Floor / Ceiling	N	
L574	Generic	1 Hour	Floor / Ceiling	N	
L577	Generic	2 Hour	Floor / Ceiling	N	
L579	Generic	1 Hour	Floor / Ceiling	N	
P522	Generic	1 Hour	Ceiling	N	
P523	Generic	1 & 1.5 Hour	Ceiling	Y	
P526	Generic	1 & 1.5 Hour	Ceiling	Y	
P528	Generic	1 Hour	Ceiling	Y	
P530	Generic	1 Hour	Ceiling	Y	
P531	Generic	1 Hour	Ceiling	N	
P533	Generic	1 Hour	Ceiling	N	
P534	Generic	1 & 1.5 Hour	Ceiling	Y	
P537	Generic	1 & 1.5 Hour	Ceiling	Y	
P540	Generic	1 Hour	Ceiling	Y	
P542	Generic	1 Hour	Ceiling	Y	
P543	Generic	2 Hour	Ceiling	Y	
P545	Generic	1 Hour	Ceiling	N	

For additional information please contact **Bill Hulstrunk, Technical Manager for National Fiber at technical@nationalfiber.com**

www.nationalfiber.com